

# Thermal Aging

## Temperature Testing

Our environmental temperature testing chambers will expose your material and/or equipment to cyclical and/or constant high or low level temperatures during testing.

**Available temperature ranges:**  
**-68°C (-90°F) to 180°C (356°F)**



## Humidity Testing

Humidity testing can be performed at the same time as temperature testing.

**Available humidity ranges:**

**10% - 98%**



**FAUSKE**  
& ASSOCIATES, LLC

WORLD LEADER IN NUCLEAR AND CHEMICAL PROCESS SAFETY

16W070 83RD STREET • BURR RIDGE, ILLINOIS 60527

(877) FAUSKE1 OR (630) 323-8750 • FAX: (630) 986-5481 • E-MAIL: [INFO@FAUSKE.COM](mailto:INFO@FAUSKE.COM) • [FAUSKE.COM](http://FAUSKE.COM)